

ROUTING

CHIEF	
DEPUTY	
OPS	
PLANS	
HOLD FOR:	
T.O.	
FILE	

*Handwritten: BX 6747 wrap up*

CXC - 2  
DOPS  
DM - 4  
COMMO - 2  
RB

IN 51950

25X1

25X1 C R E T 030052Z FEB 68 CITE

25X1

25X1

DUE TO THE LOCATION AND DESIGN OF

THE PILOT MUST TURN ON THE EMERGENCY MODE TO

25X1 ACTIVATE AND THEN TURN EMERGENCY OFF.

THIS HAS ALWAYS BEEN THE PROCEDURE AND SHOULD SHOW UP  
ON EVERY FLIGHT.

S E C R E T

3 FEB 68 57E

25X1